



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/ITS/QAR09.0004/13	Page 1 of 2
QAR Free Ref. No.:	UK: G106514988 / IT: 47612	Status: Issued
Details of change:	Additionally factory location added.	Date of issue: 2026-03-12
Location(s) audited:	Rotork Instruments Italy s.r.l. Via Portico 17 24050 Orio al Serio (BG) Italy Italy Rotork YTC Limited 81 Hwanggeum-ro 89 beon-gil Yangchon-eup, Gimpo-si 10048 Korea, Republic of	Valid until: 2027-10-28 Audit date: 2026-03-05
Issuing ExCB:	ITS - Intertek Testing & Certification Limited	
Manufacturer:	Rotork Instruments Italy s.r.l. Via Portico 17 24050 Orio al Serio (BG) Italy	
Location of Manufacturer:	Italy	
Product information:	Manufacturer of Rotary Switch boxes, Switches and Valve Control Devices	
Type of protection:	Intrinsically Safe "ia" & "ib" Flameproof Enclosure "d" Increased Safety "e" Encapsulation "ma" and "mb" Zone 2 protection "n" Dust protection by enclosure: "tD" Intrinsic Safety for Dust "iD"	

Related QARs:

GB/ITS/QAR09.0004/00	GB/ITS/QAR09.0004/01	GB/ITS/QAR09.0004/02
GB/ITS/QAR09.0004/03	GB/ITS/QAR09.0004/04	GB/ITS/QAR09.0004/05
GB/ITS/QAR09.0004/06	GB/ITS/QAR09.0004/07	GB/ITS/QAR09.0004/08
GB/ITS/QAR09.0004/09	GB/ITS/QAR09.0004/10	GB/ITS/QAR09.0004/11
GB/ITS/QAR09.0004/12		

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx EUT 17.0023X issue: 0	IECEx EUT 17.0033X issue: 0	IECEx EUT 17.0033X issue: 1
IECEx EUT 17.0033X issue: 2	IECEx EUT 17.0033X issue: 3	IECEx EUT 17.0033X issue: 4
IECEx EUT 20.0006X issue: 0	IECEx EUT 20.0006X issue: 1	IECEx EUT 21.0007X issue: 0
IECEx EUT 21.0007X issue: 1	IECEx EUT 23.0009X issue: 0	IECEx EUT 23.0009X issue: 1
IECEx EUT 24.0004X issue: 0	IECEx EUT 24.0004X issue: 1	IECEx EUT 25.0007X issue: 0
IECEx EUT 25.0007X issue: 1	IECEx ITS 09.0020X issue: 0	IECEx ITS 13.0020X issue: 0
IECEx ITS 13.0020X issue: 1	IECEx NEM 09.0020X issue: 0	IECEx SIR 12.0036X issue: 0
IECEx SIR 12.0036X issue: 1	IECEx SIR 12.0036X issue: 2	IECEx SIR 12.0036X issue: 3
IECEx SIR 12.0036X issue: 4	IECEx SIR 12.0036X issue: 5	IECEx SIR 12.0036X issue: 6
IECEx SIR 12.0055X issue: 0	IECEx SIR 12.0055X issue: 1	IECEx SIR 12.0055X issue: 2
IECEx SIR 12.0055X issue: 3	IECEx SIR 12.0055X issue: 4	IECEx SIR 12.0055X issue: 5
IECEx SIR 12.0134 issue: 0	IECEx SIR 12.0134 issue: 1	IECEx SIR 12.0134 issue: 2
IECEx SIR 14.0038X issue: 0	IECEx SIR 14.0038X issue: 1	IECEx SIR 14.0038X issue: 2
IECEx SIR 14.0038X issue: 3	IECEx SIR 14.0038X issue: 4	IECEx SIR 14.0038X issue: 5
IECEx SIR 14.0038X issue: 6	IECEx SIR 14.0038X issue: 7	IECEx ULD 21.0002X issue: 0

-- Continued on the next page



IECEX Quality Assessment Report Summary

QAR Ref. No.: **GB/ITS/QAR09.0004/13**

Page 2 of 2

Related Certificates for
previous versions (continued):

[IECEX ULD 21.0002X issue: 1](#)

[IECEX ULD 22.0024X issue: 0](#)

[IECEX ULD 22.0024X issue: 1](#)

Comments: Additional audit factory location Rotork YTC Limited performed on 04-05 March 2026.